


REPORT

TRUESDAIL LABORATORIES, INC.



CHEMISTS · MICROBIOLOGISTS · ENGINEERS
RESEARCH · DEVELOPMENT · TESTING
ESTABLISHED 1931

14201 FRANKLIN AVENUE
TUSTIN, CALIF. 92680
(714) 730-6239 • (213) 225-1564
FAX (714) 730-6462

Douglas Aircraft Company
CLIENT: Internal Mail Code 74-41
3855 Lakewood Blvd.
Long Beach, CA 90846
ATTN: Boramy Ith

REPORT DATE: June 07, 1993

RECEIVED: May 12, 1993

LABORATORY NUMBER: 59569

NPDES #CA0001414, Torrance Stormdrain,
Next to Site #799
P.O. No: T & M 25998-C

Second Quarter, 1993, Analysis as Required by the LACSD

RESULTS

Total Flow, GPD	2,173
Temperature, °F	64
pH, Units (EPA 150.1)	8.4

Parameter	Method	MILLIGRAMS PER LITER	
		Detection Limit	Concentration
Biochemical Oxygen Demand	410.4	5.0	ND
Oil and Grease	413.1	6.0	8.11
Total Suspended Solids	160.2	4.0	14.0
Settleable Solids	160.5	0.1	ND
Chromium, Total	200.7	0.01	ND

*ND = Not detected, below detection limit

Respectfully Submitted,
Truesdail Laboratories, Inc.

Thomas Herrin, Manager
Environmental Field Services



This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.